Oil Field Environmental Incident Summary

Date/Time of Notice: 12/17/2014 12:24 Incident: 20141217122424 Responsible Party: CONTINENTAL RESOURCES, INC. CONTINENTAL RESOURCES, INC. Well Name: BRANDVIK 2-25H Field Name: CORRAL CREEK Well File #: 19156 Date Incident: 12/16/2014 Time Incident: 14:00 Facility ID Number: DUNN Twp: 147 **Rna**: 96 Sec: 25 Qtr: County: Location Description: Submitted By: Todd Senescall Received By: Contact Person: Todd Boepple PO BOX 268870 OKLAHOMA CITY, OK 73126 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Other Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No **Units** Spilled Recovered Units Followup **Units** Oil **Brine Barrels** Barrels barrels Other **Description of Other Released Contaminant:** Inspected: Written Report Received: 9/23/2016 Clean Up Concluded: 12/16/2014 Risk Evaluation:

Friday, February 10, 2017 Page 1 of 2

none

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

Inquiries are being made with haulers and vendors to determine who may have been involved and the cause of the release. Standing liquid was sucked and contaminated soil removed.

Wastes Disposal Location: Liquid - SWD

Soil - Chimney Butte

Agencies Involved: Left voice mail with NDIC Inspector Ashleigh Devenberg

Updates

Date: 12/17/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, remained on location according to the report. NDIC retains oversight.